

**Golder Associates Inc.**

305 Fellowship Road, Suite 200  
Mt Laurel, NJ USA 08054  
Tel: (609) 273-1110  
Fax (609) 273-0778



July 18, 1997

Project No.: 933-6158

Ms. Sheila Sullivan (HSRM-63)  
USEPA Region 5  
Waste Management Division  
Office 4, Superfund  
77 West Jackson Boulevard  
Chicago, IL 60604

Mr. Joseph E. Trocchio  
Ohio Environmental Protection Agency  
Div. of Emergency and Remedial Response  
Northeast District Office  
2110 East Aurora Road  
Twinsburg, OH 44087

RE: NEASE SITE, SALEM, OHIO  
REMEDIAL INVESTIGATION REPORT: VOLUME 5  
APPENDIX N: MIDDLE FORK OF LITTLE BEAVER CREEK

Dear Sheila and Joe:

Please find enclosed a copy of the Appendix N revisions responding to your Comments letter dated June 30, 1997. The changes are highlighted with strikethrough and underscore to expedite your review. Also enclosed is the Response to Comments document.

Please feel free to call if you any questions.

Very truly yours,

GOLDER ASSOCIATES INC.

Todd H. Rees, Ph.D.  
Project Manager

\\ga1\_mtl1\projects\document\projects\933-6154\in rpt\apendxn\718cvltr.doc

